

The mistake of the print and the description is found in the manual that our company issued. It apologizes.

[Name of catalog]


"DeviceNet Safety NE1A Series Safety Network Controller OPERATION MANUAL"

(Publication in July, 2009) (Catalog number Z906-E1-07)

[Page of publishing]

Page 54 "Example of Connecting Two-hand Switches"

[Content of correction]



[Correction method]

We revise it at the time of a manual reprint on the next time. (The Revised version will be Rev.08.)

We attach the correction note about this in the existing manual until revised manual is published.